

Ford Combine



| Description | EPP | OEM | S/N note | Part Notes |
|-----------------|------------|-------------|------------------|---|
| TR76 | | | | |
| Compressor | 500-222 | KB402009 | | York, new w/o clutch LH suction, rotolock head, ER210 |
| Compressor | 54-037 | KB402009 | | York, reman w/o clutch LH suction, rotolock head, ER210 |
| Clutch | 600-298 | D3NN19D649A | | York, new 6.70 dia, 1 grv, 12 volt, 1.79 mounting distance |
| Expansion Valve | 904-304 | 70267 | | Oring Inlet 3/8 M, Outlet 1/2 M, 12" capillary 3/8" coil, 2 ton, ext. equalizer 13" x 1/4FO |
| Receiver Dryer | 1 804-538 | | | 3.00 x 9.00, male oring Inlet 3/8 MO x Outlet 3/8 MO, SG, FP |
| Receiver Dryer | 1 804-2010 | 763787 | may use 804-538* | 3.00 x 5.25, male oring Inlet 3/8 MO x Outlet 3/8 MO |
| TR85 | | | | |
| Expansion Valve | 904-296 | 274571 | | Oring 3/8M, 1/2M, 19" capillary 3/8 coil, 1-1/2 ton, ext. equalizer 16.5" x 1/4FO |
| Receiver Dryer | 1 804-538 | | | 3.00 x 9.00, male oring Inlet 3/8 MO x Outlet 3/8 MO, SG, FP |
| Receiver Dryer | 1 804-2010 | 763787 | may use 804-538* | 3.00 x 5.25, male oring Inlet 3/8 MO x Outlet 3/8 MO |
| TR86 | | | | |
| Compressor | 500-222 | KB402009 | 52972 & below | York, new w/o clutch LH suction, rotolock head, ER210 |
| Compressor | 54-037 | KB402009 | 52972 & below | York, reman w/o clutch LH suction, rotolock head, ER210 |
| Clutch | 600-298 | D3NN19D6498 | | York, new 6.70 dia, 1 grv, 12 volt, 1.79 mounting distance |
| Receiver Dryer | 1 804-2010 | 763787 | | 3.00 x 5.25, male oring Inlet 3/8 MO x Outlet 3/8 MO |
| Receiver Dryer | 1 804-538 | | may use 804-538* | 3.00 x 9.00, male oring Inlet 3/8 MO x Outlet 3/8 MO, SG, FP |
| TR96 | | | | |
| Compressor | 500-222 | KB402009 | 529778 & below | York, new w/o clutch LH suction, rotolock head, ER210 |
| Compressor | 54-037 | KB402009 | 529778 & below | York, reman w/o clutch LH suction, rotolock head, ER210 |
| Clutch | 600-298 | D3NN19D649A | 529778 & below | York, new 6.70 dia, 1 grv, 12 volt, 1.79 mounting distance |
| Expansion Valve | 904-304 | 70267 | 529778 & below | Oring Inlet 3/8 M, Outlet 1/2 M, 12" capillary 3/8" coil, 2 ton, ext. equalizer 13" x 1/4FO |
| Receiver Dryer | 1 804-538 | | | 3.00 x 9.00, male oring Inlet 3/8 MO x Outlet 3/8 MO, SG, FP |
| Receiver Dryer | 1 804-2010 | 763787 | may use 804-538* | 3.00 x 5.25, male oring Inlet 3/8 MO x Outlet 3/8 MO |

1: Check illustrations
 2: May require oil change
 3: New, check illustration